# This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

### IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

#### PATENT ABSTRACTS OF JAPAN

(11) Publication number:

2001228414 A

(43) Date of publication of application: 24.08.01

(51) Int. CI

G02B 26/10

B23K 26/00

B23K 26/06

// B23K101:42

(21) Application number: 2000040372

(22) Date of filing: 18.02.00

(71) Applicant:

MATSUSHITA ELECTRIC IND CO

LTD

(72) Inventor:

MEGA HIRONAO

KASAI KENJI

#### (54) GALVANOMETER CONTROLLER

#### (57) Abstract:

PROBLEM TO BE SOLVED: Ťο provide a galvanometer controller which prévents disappearance of the high-follow-up characteristic of a galvanometer to rotational drive control, is capable of having the need for correction to the characteristic fluctuation of a position sensor easily perceived by a simple means and enables an operator to carry out the correction work before the occurrence of trouble in actual working accuracy.

SOLUTION: The characteristic fluctuation of the position sensor 9 is detected by the fluctuation in the total of the positioning time measured in arbitrarily determined accordance with án positioning completion width or the fluctuation in the integrated value of the current flowing through the galvanometer 8 even when the output signal of the position sensor 9 is subjected to an influence of an environment change or change in lapse of time and a characteristic fluctuation occurs. The signal for warning the need for the correction work to this

characteristic fluctuation is outputted from a position sensor correction warning signal output means 12.

